


#### 部分的腐朽が固有振動数に与える感度














見つけにくい 部分的腐朽


アーチ端部



アーチと支柱の接合部



どこが効くのか?




# 解析モデル

去年モデル(青山2022)

 $9.60GPa = E_{r-f}$ アーチ:等方性


床版:直交異方性 = 10.29GPa


全て異方性





## で再現 =9.60GPa

今回モデル










#### 解析結果



段階的に減少!

0.4倍

0.3倍

固有振動数 12.96  $f(x) = -0.043x^2 + 0.110x + 12.926$  $\hat{R}^2 = 0.999$ 12.95 12.94 鉛直逆対称モード 12.93 0.7 0.6 ヤング率の残存率 0.4 = 0.076x + 11.05811.12  $R^2 = 0.982$ ( HZ )  $f(x) = -0.051x^2 + 0.142x + 11.039$  $R^2 = 1.000$ 鉛直逆対称モード 11.04 0.4 ヤング率の残存率 傾きで

12.99

12.97

( HZ ) 12.98

性

異

性


= 0.055x + 12.942

 $R^2 = 0.975$ 


振動数は減少した が傾向は似ている

異方性の影響は 振動数だけ?

感度を表す



### 測定値に合うまでヤング率を減少




腐朽箇所以外を一律に減少





残存ヤング率等方性 → 50%異方性 → 69%



等方性

測定値

8.69Hz

12.5 12 11.5

10.5

10


9.5


8.5

固有振動数

架設から27年経過しためおと橋の部材測定値…残存ヤング率約80%

#### まとめ





#### 今後の課題

・複数ヶ所同時腐朽時の感度解析